TAMER RING CHANGES FOR 2021

PREVIOUS RING MOUNT LOCATION

COBRA 50CC

RING P/N: HH-15

SINGLE BUTTON P/N: HH-104

DOUBLE BUTTON P/N: HH-1541

All of these part #'s will still work fine, so if you have this part #, it is OK to use.

The CX50cc Cobra's have changed to the following

NEW RING MOUNT LOCATION

COBRA 50CC

RING P/N: HH-17-1

SINGLE BUTTON P/N: HH-202

DOUBLE BUTTON P/N: HH-2521

20-21 Cobra CX-E5 Electric, 05-21 Cobra CX50 P3, CX50 Jr, CX50 Sr, CX50 FWE

PREVIOUS RING MOUNT LOCATION

COBRA 65CC

RING P/N: HH-07

SINGLE BUTTON P/N: HH-201

DOUBLE BUTTON P/N: HH-2511

All of these part #'s will still work fine, so if you have this part #, it is OK to use.

The CX65cc Cobra has changed to the following

NEW RING MOUNT LOCATION

COBRA 65CC

RING P/N: HH-17

SINGLE BUTTON P/N: HH-202

DOUBLE BUTTON P/N: HH-2521

2012 - 2021 Cobra CX65

The Cobra fork guards rub against the face of the Tamer fork ring when mounted in the previous placement. This causes premature wear on the Tamer ring at the face. Over a short amount of time, the face wears to the point that it will no longer latch and a new Tamer ring is needed.

PREVIOUS RING MOUNT LOCATION

KTM, HUSQ, GASGAS 50CC

RING P/N: HH-17

SINGLE BUTTON P/N: HH-202

DOUBLE BUTTON P/N: HH-2521

The 50cc KTM, Husq. and GasGas has changed to the follow-ing

NEW RING MOUNT LOCATION

KTM, HUSQ, GASGAS 50CC

RING P/N: HH-15

SINGLE BUTTON P/N: HH-104

DOUBLE BUTTON P/N: HH-1541

'02-'21 KTM 50SX, 50SX FE, 50SX Mini

'16-'21 Husq. TC50, '20-'21 Husq. TC EE 5 Elec - '20-'21 KTM 50SX-E 5 Elec.,

'21 Gas Gas MC-E5 Electric, MC50

The product instructions at www.tamermx.com have all been updated to the new changes

FILE UPDATED 6/30/21